

DESCRIPTION

HEAT TREATMENT PROCESS FOR FINE
CARBON FIBER POWDER AND HEAT TREATING EQUIPMENT

5

Technical Field

The present invention relates to a production process for a fine carbon fiber material which is excellent in characteristics such as electron emitting ability, hydrogen storage ability, electroconductivity and thermal conductivity and which is used for various secondary batteries including a Li ion battery, fuel cells, FED, superconductive devices, semiconductors and electroconductive composite materials and production equipment, more specifically to a heat treatment process for turning vapor grown carbon fibers produced by a CVD process under non-oxidative atmosphere, single-walled and multiwalled carbon nanotubes or mixtures of the above carbon nanotubes into products having a required quality and heat treatment equipment.

15
20

Background Art

A lot of unreacted organic compounds and polymers are sometimes contained as volatile tarry matters in so-called as-grown products taken out from a reaction

25

furnace in the case of vapor grown carbon fibers and carbon nanotubes produced by a CVD process. It is known that the above as-grown carbon fibers and carbon nanotubes in which the unreacted organic compounds and polymers are adsorbed on surfaces cause ~~troubles in a~~ treating problems in subsequent treatment steps when they are processed into composite materials, and that they have inferior crystallinity so that heat treatment is required in order to remove volatile components and to improve the crystallinity. In order to ~~surely~~ effectively carbonize and crystallize ~~the above fibers and nanotubes with the above tarry matters~~ fibers and nanotubes that have the above-mentioned volatile compounds (which may be high or low boiling-point carbon compounds), which are carbon components having a low boiling point or a high boiling point volatilizing, ~~carried out is a~~ two stage treatment process may be carried out. in which In such a treatment process, the above volatile components are burned in advance at a temperature of, for example, 1500°C or lower and then heat treatment for carbonization and crystallization is carried out at 2000 to 3000°C. In these processes, however, the fibers or the nanotubes are filled into a vessel such as a crucible and a boat, or compaction-
molded and then subjected to heat treatment batchwise

(Japanese Patent Application Laid-Open No. 021911/1985,
 Japanese Patent Application Laid-Open No. 133120/1987,
 Japanese Patent Application Laid-Open No. 191515/1987,
 Japanese Patent Application Laid-Open No. 006624/1990,
 5 Japanese Patent Application Laid-Open No. 101118/1994,
 Japanese Patent Application Laid-Open No. 212517/1994,
 Japanese Patent Application Laid-Open No. 025626/1998,
 Japanese Patent Application Laid-Open No. 312809/1998 and
 Japanese Patent Application Laid-Open No. 208145/2000).

10 Vapor grown carbon fibers and carbon nanotubes have
 a very small bulk density of 0.1 g/cm^3 or less, and
 therefore heat treatment equipment having a very large
 volume is required in order to ~~subject-process large~~
~~quantities of them to heat treatment in a large amount.~~
 15 Accordingly, the actual industrialization thereof
 requires an enormous cost of facilities and energy. ~~Then,~~
~~the actualization of~~ Furthermore, realizing an
industrially feasible process ~~which can industrially be~~
~~operated requires~~ requires an increase in the bulk
 20 density of the processed material and a reduction in the
size of the processing facilities. ~~, and therefore~~
~~employed is~~ These requirements favor a process in which
 the above fibers or nanotubes are filled into a vessel or
 are compaction-molded and then subjected to heat
 25 treatment. However, the following problems are involved

in those processes.

A) Problems in a process in which they are filled into a vessel

1) The vessel is a graphite crucible, and a graphite
5 crucible having a large volume is required for treatment
in a large quantity, so that the cost ~~therefor~~ thereof is
increased.

2) If pressure is not applied when filling ~~into~~ the
vessel, the amount to be filled is extremely small, ~~and~~
10 ~~the efficiency is inferior~~ reducing processing efficiency.

3) When using a crucible, the bulk density is 150 kg/m^3
or less at most, even if applying pressure, and the
weight of the product is very small as compared with the
weight of the vessel.

15 4) Accordingly, a greater part of energy used is consumed
for heating the vessel.

5) The filling device is large-scaled, and a cost for the
device is required.

6) Taking the facility cost and the operation cost into
20 consideration, the product is commercially expensive.

B) Problems in a compaction-molding process

1) Even if compaction-molded, a bulk density of the
molded article can not be larger than 150 kg/m^3 .

2) Even if compaction-molded, the volume is expanded due
25 to elasticity of the fibers when ~~releasing~~ pressure

~~applied~~ is released.

3) It is difficult to apply even pressure to the inside of a fiber aggregate in a powder compressing operation, and molding is not easy.

- 5 4) The molded article has a low density and is expanded due to elasticity, and therefore the molded article does not have sufficient strength for operation. The expansion due to elasticity caused when releasing pressure ~~applied to~~ from the compaction-molded powder
- 10 ~~brings about~~ causes the collapse of the molded article, ~~to~~ turning it into disordered amorphous powder which can not transmit force, ~~and the~~ The fibers in this collapsed part bring about clogging in the furnace or in a transferring conduit of the molded article. In addition
- 15 thereto, the smaller the fiber diameter is, the greater the expansion caused due to the elasticity after compacting the fibers is, and therefore the above clogging is more liable to be caused. Accordingly, troubles are liable to be caused in a step where fine
- 20 carbon fibers are subjected to heat treatment.

However, it has so far been considered that in a process in which powder is subjected to heat treatment as it is continuously, or batchwise, discharged from a reaction furnace ~~is subjected as it is continuously or~~

25 ~~batchwise to heat treatment heat efficiency is~~

~~lowinefficient, and that~~ heat treatment is unsufficiently
 carried out, ~~and, therefore it is not yet reported~~
~~to~~ Therefore no attempts have yet been made carry out heat
 treatment by such a process on an industrial level.

5 As described above, in a process in which filling
 into a vessel or compaction-molding is carried out,
 complication in the equipment and increase in the
 equipment cost and the production cost brought about
 thereby make it difficult to carry out heat treatment
 10 commercially efficiently. An object of the present
 invention is to ~~newly~~ provide a new process in which fine
 carbon fibers are subjected to heat treatment at a low
 cost in a large amount to allow crystallization thereof
 to proceed. ~~and~~ Another object of the present invention
 15 is to provide equipment for the above process.

Disclosure of the Invention

In the present invention, the fine carbon fibers
 mean fine fibrous carbon materials such as vapor grown
 20 carbon fibers (VGCF), carbon nanotubes, carbon nanocones,
 carbon nanocoils and ribbon-shaped carbon fibers.

The characteristics of carbon base fiber materials
 such as a vapor grown carbon fiber and a carbon nanotube
 are related closely to the crystallinity thereof.
 25 ~~Earnest researches repeated~~ Repeated experiments by the

~~present inventors have resulted in finding such knowledge~~
~~contrary to a conventional common sense that shown,~~
~~unexpectedly, that a~~ vapor grown carbon fiber and a
carbon nanotube, ~~to be surprised,~~ not only have good
5 heat conductivity but also rise in crystallinity for very
short time. Accordingly, it has been found that
sufficient heat treatment can be achieved by treating the
powder as it is, or by treating the amorphous powder
obtained by crushing the compressed powder, and that use
10 of such a process makes it possible to far more
efficiently carry out crystallization, ~~and thus the~~
~~present invention has been completed.~~

~~Paying attentions to~~ In light of the very good heat
conductivity of the above substances, the present
15 ~~invention has been developed and it provides a process in~~
~~which the~~ where powder discharged from a reaction furnace
is subjected ~~as it is~~ directly to heat treatment "as-is,"
or where ~~the~~ amorphous powder obtained by crushing the
compressed powder is treated to crystallize it. ~~and The~~
20 present invention also comprises equipment used for the
above process.

The present invention is characterized by:

- 1) a process in which fine carbon fibers are charged into
a heating furnace in the form of powder to carry out heat
25 treatment without filling them into a specific vessel or

compaction-molding them, that is, a powder heat treatment process in which vapor grown carbon fibers, carbon nanotubes and the like are heated in the form of powder taken out from a reaction furnace at a temperature of
 5 800°C or higher under inert gas atmosphere or hydrogen gas atmosphere, and the equipment used for this~~the~~ process; or

2) a process in which fine carbon fibers are once compressed and then crushed to turn them into amorphous
 10 powder and in which they are then subjected to heat treatment at a temperature of 800°C or higher under an inert gas atmosphere or a hydrogen gas atmosphere, and the equipment used for ~~the~~ this process.

The fine carbon fibers are subjected to heat
 15 treatment in the form of the powder having fluidity by the above processes of 1) or 2), and therefore the phenomenon of clogging of ~~the~~ equipment due to ~~the~~ collapse of ~~the~~ compaction-molded article-articles subjected to heat treatment can be avoided.

20 Compressing and crushing in the present process are carried out before the heat treatment. The powder after crushing has a bulk density of preferably 15 to 35 kg/m³, more preferably 20 to 30 kg/m³.

Further, the present invention is characterized by
 25 the following.

- 3) A treatment temperature in the inside of the furnace is 800°C or higher, and preferably carried out are (1) first stage heat treatment in which volatile components stuck to the fine carbon fibers are vaporized at a temperature of 800 to 1500°C and (2) second stage heat treatment in which ~~they~~ the carbon fibers are then carbonized at 1300 to 3000°C.
- 4) Inert gas such as argon, helium and xenon or hydrogen is used as a surrounding gas ~~in the heat treatments to~~ carry out the heat treatments under an inert or reducing atmosphere. It is also possible to partially add a hydrocarbon gas. The surrounding gas may be allowed to flow in any direction. It is preferable ~~to~~ that the surrounding gas flow from a discharging port side of the powder to a charging port side thereof, and in the case of the second stage, it is preferable that the surrounding gas be allowed to flow ~~preferably~~ from a side which is gravitationally positioned at a lower part to a side which is positioned at an upper part.
- 5) An inflow port and a discharge port of the gas are preferably provided separately in parts close to a charge port and a discharge port of the powder.
- 6) The inside of the heating furnace may be partitioned by push-in plates or stirring devices, and a gas discharge pipe is provided in a part which is in the

compartment closest to a raw material charging side and which is as hot as possible in the vicinity of a raw material charge port when partitioned by these plates or stirring devices and in the part described in ~~above~~ 5) when not partitioned, and preferably in a part of 1500°C or higher. A trap for carried components such as the catalyst components, the fine carbon fiber powder, and the like contained in a waste gas and a waste gas treatment apparatus for treating tar and the like are provided at a downstream side of the gas discharge part.

7) A gas storing tank in which gas can be stored is disposed before or after the discharge port of the carbon fiber powder in the heat treatment equipment, and this storing tank is connected to the heating furnace. A mechanism which can shut the storing tank is provided in the above connecting part. An inner pressure of the storing tank is raised higher than that of the heating furnace in shutting the storing tank, and pressure accumulated therein is released into the heating furnace by opening the shutting mechanism to send a pressure fluctuation wave into the heating furnace. The above accumulated pressure is enough if it is higher by 1 kPa or more than a pressure in the inside of the heating furnace, and it may be higher by 5 kPa or more, and further by 20 kPa or more. The pressure fluctuation wave

is preferably transmitted intermittently, and the cycle thereof is preferably 10 to 120 seconds, more preferably 30 to 60 seconds.

An apparatus for transmitting a pressure fluctuation wave to the heating furnace may also be used as a push-out apparatus for sending the carbon fiber powder subjected to heat treatment from the above powder discharge port to ~~the~~ a subsequent processing or treatment step, and in this case, a push-out plate becomes the shutting mechanism described above.

8) The heating furnace is a vertical furnace having an angle of 0° or more to 90° from a horizontal plane, and it is preferably perpendicularly disposed.

The heating furnace has a tube in which a cross-sectional form is circular, ellipsoidal, polygonal or rectangular, and a heating part is provided in the furnace. The heating method may be either of a method in which a furnace core tube is directly heated by a high-frequency wave and a method in which the furnace core tube is heated by means of a resistance heating device.

The fine carbon fibers are allowed to gravitationally fall in the above furnace, whereby they are continuously transported in the heating furnace.

9) Provided in the powder heat treatment equipment described above are a charging device for charging the

fine carbon fibers ~~to~~ into the heating furnace described above, a surrounding gas-feeding device for feeding an inert gas or a hydrogen gas to the heating furnace, a collecting device for collecting the fine carbon fibers
5 from the heating furnace, a controlling device for controlling flow of the powder in the inside of the heating furnace and a trap for trapping carried components contained in a waste gas coming from the heating furnace.

10 According to the process of the present invention, a crucible or a molding apparatus ~~by~~ for compaction-filling is not required, and therefore the equipment cost is markedly ~~inexpensive~~ reduced as compared with those ~~ina~~ conventional heat treatment process. Further, energy
15 for heating a crucible is not required, ~~and it can be expected to a large extent that~~ which may significantly reduce the operating cost ~~is reduced~~. In addition thereto, the equipment is simplified, so that ~~troubles~~ opportunities for equipment failure and malfunction are
20 reduced.

Brief Description of the Drawings

Fig. 1 is a schematic drawing of heat treatment equipment of a batch process used in Example 1.

25 Fig. 2 is a schematic drawing of heat treatment

equipment of a continuous process used in Example 2.

Fig. 3 is a schematic drawing of heat treatment equipment of a semi-batch/continuous process used in Example 3.

5 Fig. 4 is a chart of differential thermal analysis of the fine carbon fibers before subjected to heat treatment in Example 2.

Fig. 5 is a chart of differential thermal analysis of the fine carbon fibers after subjected to heat
10 treatment in Example 2.

Best Mode for Carrying Out the Invention

The present invention can be carried out by any one or combination of three kinds of batch process,
15 continuous process and semi-batch and/or continuous process.

Powder heat treatment equipment of a batch process is powder heat treatment equipment installed a tubular or cylindrical heating furnace placed at an optional
20 constant angle between ~~verticality and horizontality~~ 0 and 90 degrees away from horizontal, wherein the above heating furnace is equipped with a push-in device that may be driven by reciprocating motion for the fine carbon fibers subjected to heat treatment, and also with a shutting
25 plate. It is characterized by having a holding plate for

preventing short-cut of a non-heated portion of the powder at the lower part and a push-in plate having a function of compressing and/or scratching off the powder at the upper part of the furnace. The above push-in
5 plate and holding plate are driven alternatively or according to a fixed time schedule to subject the powder introduced from the upper part to heat treatment batchwise.

A powder heat treatment equipment in a continuous
10 process is a powder heat treatment equipment installed a tubular or cylindrical heating furnace of a vertical type placed at an angle which is larger than 0 degree from a horizontal plane and which is sufficient for making it possible to allow the powder to flow by means of gravity,
15 wherein the fine carbon fibers are continuously transferred in the above furnace with flowing by means of gravity.

The powder, which is compressed and crushed, is introduced into the furnace from the upper part and piled
20 therein. ~~Such powder is very excellent in an operating property in the point that it~~ Because the above powder is not turned into disordered amorphous powder which can not transmit force. ~~In this case, the above powder, it is~~ not compressed and molded in the furnace because of a
25 very small specific gravity and high elasticity. That is,

in the heating furnace in the powder heat treatment equipment of the present invention, a pressure of the powder on the lowest face of the powder in the furnace is preferably 2 kPa or less, more preferably 1.5 kPa or less and most preferably 1.1 kPa or less. If the pressure falls in the above range, ~~compressing and molding of the carbon fibers do not take place~~the carbon fibers do not need to be compression molded, and therefore clogging of the pipe caused by crushing thereof can effectively be prevented. For example, when the powder is piled 10 m high, a pressure on the lowest face of the powder is merely 0.294 kPa when the bulk density is 30 kg/m³, and it is merely about 1 kPa in the case of 100 kg/m³. According to Japanese Patent Application Laid-Open No. 60444/1996, it is described that a pressure required for molding the fine carbon fibers is 0.1 kg/cm² (= 9.81 kPa) or more. Based on this, the pressure ~~exemplified above~~which is brought about by and caused above by the own weight of the powder is not sufficient for compressing the powder.

The powder subjected to heat treatment is discharged from the lower part of the heating furnace. The discharge mechanism at the lower part is a reciprocating type pushing-out device, and therefore a weak pressure fluctuation can be given to the inside of

the heating furnace by feeding a gas to a connecting rod side of a piston when the powder ~~are~~is pushed out by a push-out plate.

A furnace core tube is preferably cylindrical. A
5 caliber of the furnace core tube is preferably 1000 mm ϕ or less, more preferably 700 mm ϕ or less and most preferably 500 mm ϕ or less. If it falls in the above range, a heat transfer efficiency such that the carbon fibers moved by an own weight thereof are sufficiently
10 heated can be obtained.

Powder heat treatment equipment ~~of~~for a semi-batch and/or continuous process is powder heat treatment equipment which is installed a lateral heating furnace disposed horizontally or almost horizontally and which is
15 a tubular or cylindrical furnace having a circular, ellipsoidal, polygonal or rectangular cross-sectional form, and wherein plural push-in plates which do not completely shut up the inner wall of the furnace are disposed on a driving shaft disposed so as to pass
20 through the center of the furnace; the above driving shaft rotates and reciprocates in a horizontal direction; the furnace has a heating part in an inside thereof; and the fine carbon fibers are moved semi-batchwise or continuously. It is equipment in which the powder is
25 pushed in and moved continuously and/or batchwise by

charging the powder from a raw material-charging device continuously and/or batchwise and repeating rotation and reciprocation of the driving shaft ~~capable of rotating and reciprocating and~~ equipped with flat or curved push-in plates, and in which the treated fibers are taken out from the lower part in a downstream. The form of the above push-in plates shall not be restricted as long as they are flat or curved and have a structure in which residence of the powder can be controlled, and they can be mounted as well at a fixed spacing and/or a fixed angle. Further, they can assume as well a structure in which the shaft is parallel vibrated or rotationally vibrated. This makes it possible to control a residence time of the powder and improve the heat transfer efficiency by bringing the powder into contact with the inner wall face of the furnace. ~~When the treating temperature is~~ In embodiments of the invention that reach temperatures of 1500°C or higher, the materials of the mechanical parts are preferably ceramic materials and graphite materials.

A method suited to the target temperature can be selected as a heating means for the heating furnace, and ~~a methods~~ such as resistance heating ~~and or~~ high-frequency heating can be employed. In the case of 2000°C or higher, high-frequency heating is preferred. The

material suited to the heating method can be selected,
and a graphite material is preferred in the case of high-
frequency heating.

5

Examples

Next, the present invention shall be explained in
further details with reference to examples, but the
present invention shall by no means be restricted to the
examples described below.

10

Example 1

Batch process equipment

Carried out by equipment shown in Fig. 1.

It is a vertical batchwise heating furnace having
15 an inner diameter of 200 mm, and it is equipped at an
upper part with a charging device (7) for as-grown fine
carbon fibers to be subjected to heat treatment and a
driving mechanism (9) for moving upward and downward a
push-in plate (1) for pushing in and scratching off the
20 above material. A discharge port for a waste gas is
disposed at an upper part of a heating part. Disposed at
the lower part is a collecting mechanism comprising a
collecting tank (8) for collecting the above fine carbon
fibers after they are subjected to heat treatment, a
25 discharge plate (5) for discharging the carbon fibers

subjected to heat treatment and a driving mechanism (10) ~~therefor~~ for driving said discharge plate and a holding plate (4) for preventing the untreated carbon material from leaking and a driving mechanism (11) ~~therefor~~ for driving said holding plate. The above holding plate is reciprocated alternatively between a position of an end A of a soaking part and a position of B in which a scratching operation is able to be carried out. Inert gas for controlling the atmosphere is introduced from a holding plate-receiving part of the lower part and discharged from a discharging port at the upper part of the heating part.

In Fig. 1, (2) is a heater; (3) is a high-frequency oscillating coil; and (6) is a heat insulating material.

Operating procedure

The procedure shall be explained according to Fig. 1.

A surrounding gas is allowed to flow.

The push-in plate is elevated up to the upper end.

The holding plate is raised to the position of A to inhibit the untreated carbon raw material (as grown) from leaking.

The fine carbon fiber material is introduced.

The carbon fibers are homogenized while moving the push-

in plate up and down several times, and then the push-in plate is allowed to go down to the position of C to compress the above carbon fibers.

Driving is stopped in the above position for fixed time
 5 to heat the carbon fibers until they are soaked.
 After completing the heat treatment, the holding plate is lowered to the position of B.
 The push-in plate is lowered to the position of A while being pushed in.

10 The above carbon fibers which have finished treatment are discharged by a discharging plate.
 The discharging plate is returned to the initial position.
 The push-in plate is elevated up to the upper end.
 The holding plate is raised to the position of A.
 15 The cycle described above is repeated.

Operating conditions and results

Heating furnace temperature: 2800°C

Soaking part length: 600 mm

20 Argon flow rate: 10 L/min

Raw material: carbon nanotube (as grown)

Charging amount: 1 kg/cycle

Heating time: 5 minute

Raw material d_{002} (interplanar spacing) = 0.369 nm

25 d_{002} after treated at 2800°C: 0.339 nm

Example 2

Continuous process equipment

Carried out using equipment shown in Fig. 2.

5 It is a continuous system heating furnace having an inner diameter of 350 mm ϕ and a heating part length of 1250 mm, wherein it is equipped with a charging device (22) for charging as-grown fine carbon fibers which are compressed and then crushed and a waste gas-discharging device at the upper part, and the surrounding gas introduced from the lower part of the equipment is discharged from the waste gas-discharging device. Disposed at the lower part is a collecting device comprising a collecting part (27) for collecting the above carbon fibers after they are subjected to heat treatment, a discharging plate (24) for discharging the above powder after it is subjected to heat treatment and a driving device (25) ~~therefor~~ for driving said discharging plate. A surrounding gas-feeding device is present at a driving device side (26) of the discharging plate (24), and when the discharging plate is in the position of A, a pressure in the inside of a chamber on the side (26) is set up higher by 1 kPa than that of the heating furnace main body (21).

Operating procedure and conditions

The procedure shall be explained according to Fig. 2.

A surrounding gas is allowed to flow (superficial
5 velocity: 10 mm/sec).

The furnace is heated (low temperature treatment: 900°C).

The fine carbon fiber powder is introduced (residence
time: 8 minutes and bulk density: 30 kg/m³).

The powder falling to the collecting part (27) by virtue
10 of gravity are discharged by the discharging plate (24).
A cycle time of the discharging plate (24) is 30 seconds.
Accordingly, a cycle time of pressure fluctuation given
to the inside of the heating furnace is 30 seconds.

In Fig. 2, (23) represents a high-frequency coil,
15 and (28) represents a heating part (furnace core) in the
furnace.

Results

Comparison between before and after treatment was
20 carried out by differential thermal analysis to find that
volatile components were removed.

A differential thermal analytical chart of the fine
carbon fibers before treatment is shown in Fig. 4, and a
differential thermal analytical chart of the fine carbon
25 fibers after treatment is shown in Fig. 5.

Example 3

Semi-batch/continuous process equipment

Carried out using equipment shown in Fig. 3.

5 It is a lateral batchwise heating furnace having an inner diameter of 200 mm, and push-in plates (33) are mounted on a movable shaft (34) disposed in a longitudinal direction of the furnace. ~~This~~ A push-in plate ~~has~~ may have a notch part in a radius direction,

10 giving it and assumes a structure in which itsuch that the plate does not completely shut up a conduit. In the present example, a structure in which a segment of a circle is cut out has been assumed as shown in Fig. 3. The number of the push-in plates may be set up according

15 to a push-in distance, and five plates of (a), (b), (c), (d) and (e) have been set in the present example.

Further, the push-in plates are fixed on the movable shaft, and the fixing directions are set up so that the notch parts of the respective plates are overlapped when

20 observing them along the shaft. The above movable shaft is prepared from a graphite material. The positions of the respective push-in plates in the axial direction may be disposed evenly or unevenly. The intervals may be different in the outside part of the soaking part. The

25 plates have been disposed at an equal interval in the

present example. The driving directions of the push-in plates are a direction in which the plates are reciprocated by a fixed distance along the shaft and a direction in which the shaft is rotated or reciprocated and rotated by a step motion of every 180 degrees, and they are driven by means of a driving device (35).

In Fig. 3, (31), (32) and (37) are a heater, a heat insulating material and a product collecting device respectively.

10

Operating procedure

The procedure shall be explained according to Fig. 3.

A surrounding gas is allowed to flow, and the furnace is heated.

In starting the operation, the push-in plate (a) is placed in the position of A with the push-in part turned downward. In this case, the plate (e) is positioned at an end E of the heating part.

20 A raw material, in the form of carbon nanotubes (as grown), is charged from a raw material charging device (36) to a space between (a) and (b).

After charging a fixed amount of the above raw material, the push-in plate (a) is pushed in to the position of B.
25 In this case, five plates move at the same time, and the

plate (e) comes to the position of F.

The plate is rotated by 180 degrees in the above position to replace the upper and lower parts of the plates (the plate is rotated by half round, and the upper and lower
5 parts are replaced).

The push-in plate (a) is pulled back from the position of B to the position of A. The raw material is present between (b) and (c). The push-in plate is rotated by half round in the above position.

10 The raw material is charged to a space between (a) and (b).

After charging a fixed amount of the above raw material, the push-in plate (a) is pushed in to the position of B. The push-in plate is rotated by half round in the above
15 position.

The push-in plate (a) is pulled back from the position of B to the position of A. The raw material is present between (b) and (c) and between (c) and (d).

The push-in plate is rotated by half round in the above
20 position.

The raw material is charged to a space between (a) and (b).

After charging a fixed amount of the above raw material, the push-in plate (a) is pushed in to the position of B.
25 The push-in plate is rotated by half round in the above

position.

The push-in plate (a) is pulled back from the position of B to the position of A. The raw material is present between (b) and (c), between (c) and (d) and between (d) and (e).

The push-in plate is rotated by half round in the above position.

The raw material is charged to a space between (a) and (b).

After charging a fixed amount of the above raw material, the push-in plate (a) is pushed in to the position of B. In this case, the nanotubes present between (d) and (e) finish heat treatment and are transferred to a space between E and F, and therefore they are transferred to the collecting device.

The raw material powder, charged from the charging port, ~~are~~ is pushed in to the downstream direction while subjected to heat treatment in order by repeating the above operation, and ~~they are~~ then discharged from the end part.

Operating conditions and results

Heating furnace temperature: 2800°C

Soaking part length: 600 mm

Argon flow rate: 10 L/min

Raw material: carbon nanotube (as grown)

Charging amount: 1 kg/5 minute

Raw material d_{002} : 0.370 nm

d_{002} after treated at 2800°C: 0.337 nm

5

Industrial Applicability

The fine carbon fiber produced by the process of the present invention has excellent characteristics such as electron emitting ability, hydrogen storage ability, electroconductivity and thermal conductivity, and it is
10 used for various secondary batteries including a Li ion battery, fuel cells, FED, superconductive devices, semiconductors and electroconductive composite materials.